8-morecony 5-5-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to:

PHOTO DATE:

Mulberry (Thomas Broughton Plantation House)
Cooper River, West Branch
Moncks Corner vicinity
Berkeley County
South Carolina

November 1978

HABS No. SC-393

Photo SC-393-1 was previously transmitted to the Library of Congress.

The photos below were taken for the 1977-79 South Carolina project made possible by grants from the National Endowment for the Arts. Charles N. Bayless, AIA, was the photographer.

SC-393-2 GENERAL VIEW, FROM SOUTHWEST. Note front and rear corner pavilions, which are original with house. SC-393-3 SOUTH (FRONT) SIDE SC-393-4 NORTH (REAR) SIDE. Shed roofed porch built ca. 1930. Brick-face dormer not original with house, date unknown. SC-393-5 EAST SIDE, SHOWING THE MAIN CORE AND SOUTHEAST (front) AND NORTHEAST (rear) CORNER PAVILIONS SC-393-6 WEST SIDE, LOOKING NORTH. Note watertable of tile which copies original brick. a few of which remain. SC-393-7 MAIN ENTRY, SOUTH (FRONT) ELEVATION SC-393-8 MAIN ENTRY, PEDIMENT DETAIL. Ornament reputedly a copy of original found in attic during 1920 restoration. SC-393-9 NORTH (REAR) SIDE, ENTRY AND STAIRHALL DORMER. This dormer not original with house; note Flemish bond brickwork v.s. English bond brickwork of front and side elevations. ENTRY TO NORTHWEST CORNER PAVILION. Door of northeast corner SC-393-10 pavilion same.

(continued on page 2)

MULBERRY (Thos. Broughton Plantation House) Index To Photographs HABS No. SC-393 (page 2)

SC-393-11	DETAIL STUDY OF A TYPICAL CORNER PAVILION (located on southwest corner of house)
SC-393-12	DETAIL STUDY: THREE DIFFERENT TYPES OF WINDOW TRIM, RAKING BRICK CORNICE AND SECOND FLOOR STRINGCOURSE. (Located at northwest corner of house)
SC-393-13	DETAIL STUDY: CHIMNEY, BRICK CORNICES AND ROOF OF SOUTHWEST CORNER PAVILION
SC-393-14	TYPICAL WEATHER VANE OF A CORNER PAVILION. Note date, which has not been proved nor disproved.
SC-393-15	TREE-LINED DRIVEWAY LEADING TO PLANTATION, FROM WEST
SC-393-16	LIVE OAK TREES (QUERCUS VIRGINIANA). On driveway leading to plantation
SC-393-17	FIRST FLOOR STAIRHALL LOOKING NORTHWEST, SHOWING NORTH REAR ENTRY. It has not been determined whether this hall is original with the house.
SC-393-18	FIRST FLOOR, STAIRHALL, LOOKING SOUTHWEST INTO SOUTHEAST AND NORTHWEST ROOMS. Note paneled jambs of opening to southeast room.
SC-393-19	FIRST FLOOR, STAIRHALL (north part of house): STAIR DETAIL
SC-393-20	FIRST FLOOR, SOUTHEAST ROOM, NORTH (right) AND WEST WALLS. All woodwork is ca. 1800.
SC-393-21	FIRST FLOOR, SOUTHEAST ROOM, NORTH WALL: CA. 1800 MANTLE
SC-393-22	FIRST FLOOR, SOUTHEAST ROOM: ENTRY FROM SOUTH
SC-393-23	FIRST FLOOR, SOUTHEAST ROOM: CORNICE DETAIL. The paneled wall below is part of chimneypiece.
SC-393-24	FIRST FLOOR, NORTHEAST ROOM, SOUTH WALL
SC-393-25	FIRST FLOOR, NORTHEAST ROOM, SOUTH WALL: MANTLE DETAIL
SC-393-26	FIRST FLOOR, SOUTHWEST ROOM (DINING ROOM), NORTH WALL. Shell cupboard is ca. 1930. Cornice, chimneypiece and door are ca. 1800.

MULBERRY (Thos. Broughton Plantation House) Index To Photographs HABS No. SC-393 (page 3)

SC-393-27	FIRST FLOOR, SOUTHWEST ROOM (DINING ROOM), NORTH WALL: MANTLE (ca. 1800)
SC-393-28	FIRST FLOOR, SOUTHWEST ROOM (DINING ROOM), NORTH WALL: CORNICE DETAIL (at intersection of wall and chimneypiece)
SC-393-29	FIRST FLOOR, SOUTHWEST CORNER PAVILION, LOOKING NORTHEAST
sc-393-30	SECOND FLOOR, NORTHEAST ROOM, SOUTH WALL. Bolection mold fireplace surround probably original with house and only remaining one thus. Note bolection panel molds on raised-panel door, also probably original with house.
SC-393-31	SECOND FLOOR, NORTHWEST ROOM, SOUTH WALL. Three raised-panel doors with bolection panel molds, all probably original with house.
SC-393-32	SECOND FLOOR, SOUTHWEST ROOM, NORTH WALL. Flat-panel door is ca. 1800. The raised-panel door is probably original with house. Also note mantle.